LEGEND:

FIBERS SITE BOUNDARY

FENCE

ROAD

ELECTRIC POLE

LAMP POLE

----- SWALE

+----- RAILROAD TRACKS

DIRT ROAD

- GROUNDWATER MONITOR WELL
- GROUNDWATER EXTRACTION WELL
- GROUNDWATER MONITOR CLUSTER WELL
- GROUNDWATER PRODUCTION WELL
- GROUNDWATER PRODUCTION WELL NOT IN USE

TOTAL HALOETHERS ISOCONTOUR WITH GROUNDWATER CONCENTRATION (MICROGRAMS PER LITER [µg/L]) DASHED WHERE INFERRED

- 17.3 TOTAL HALOETHERS GROUNDWATER CONCENTRATION (µg/L)
- CONCENTRATION EXCEEDS 124 GROUNDWATER CLEANUP CRITERIA (GWCC) OF 100 µg/L
- THE ANALYTE WAS ANALYZED FOR BUT NOT DETECTED AT THE REPORTING LIMIT OR METHOD DETECTION LIMIT INDICATED
- NOT SAMPLED
- GROUNDWATER NOT ENCOUNTERED
- PR-3 PUERTO RICO HIGHWAY 3

FIBERS PUBLIC SUPPLY WELLS SUPERFUND SITE GUAYAMA, PUERTO RICO
SECOND SEMI-ANNUAL GROUNDWATER **MONITORING REPORT FOR 2016**

> **TOTAL HALOETHERS ISOPLETH MAP** (MARCH-MAY 2015)



FIGURE C-14